

Attachment 0026

Technical Document Discrepancies

1. Attachment 0008 - MWO 9-2350-403-55-1 (T161 Track System): MWO 9-2350-403-55-1 inadvertently omits Part Number 12555909, End Connector Puller under Special Tools. This tool is required for T161 Track removal and installation.
2. Attachment 0009 - 57K6627 T161 Track Mod Kit – incorrectly lists the Puller Tool Assembly (P/N 12555909) as one of the parts in the kits. This item should be issued as BII (reference Attachment 0021).
3. Attachment 0011- MWO 9-2350-408-55-4 (Heavy Weight Torsion Bar):
 - a. MWO 9-2350-408-55-4 inadvertently omits Part Number 12296921, Seal. This item is required for Torsion Bar installation.
 - b. MWO 9-2350-408-55-4 inadvertently omits Part Number 12298145 under Special Tools. . This item is required for Torsion Bar removal and installation.
 - c. MWO 9-2350-408-55-4 inadvertently omits Part Number 12296957 under Special Tools. This tool is required for Torsion Bar assembly.
4. Attachment 0012 - Heavy Weight Torsion Bar Mod Kit 57K6681: The Heavy Weight Torsion Bar Kit incorrectly lists the Washer Part Number as 80064-2586895. The correct Part Number is 2586895.
5. Attachment 0017 - MWO 9-2350-408-55-3 (Vehicle Suspension Roadarm System):
 - a. MWO 9-2350-408-55-3 incorrectly lists the Support Assembly Part Number as 12520458-1. The correct Part Number is 12520468-1.
 - b. MWO 9-2350-408-55-3 incorrectly lists the Support Assembly Part Number as 12520458-2. The correct Part Number is 12520468-2.
6. Attachment 0018 - Vehicle Suspension Roadarm System Mod Kit 57K6692: The Vehicle Suspension Roadarm System Mod Kit incorrectly lists the Washer Part Number as 80064-2586895. The correct Part Number is 2586895.