

CONTINUATION SHEET**Reference No. of Document Being Continued****Page 2 of 2**

PIIN/SIIN W56HZV-04-P-1379

MOD/AMD P00001

Name of Offeror or Contractor: U.S.HARDWARE SUPPLY INC.

SUPPLEMENTAL INFORMATION

1. The purpose of this modification is to clarify the kit list; due to a conflict in the Technical Data Package.
2. The Special Packaging Instruction (SPI) #AK 15047397 erroneously lists three parts that are not part of the kit, shows the quantity for two items inaccurately, and has the wrong character in four (4) part numbers. The list found on drawing 57K4216 is correct.
3. The following parts are erroneously listed on the SPI:

Strap, Tiedown	SAE-AS33671-7
Washer	MS51414-3
Screw	B1821BH038C113N
4. The following parts show their proper quantities:

Washer, Strap Adjust	10910174-22	8 each
Screw	B1821AH038C100N	2 each
5. The following parts reflect their accurate part numbers:

Screw	B1821AH038C138N
Screw	B1821AH025C063N
Screw	B1821AH038C100N
Screw	B1821AH025C056N
6. Sections B and C of the SPI are affected by these clarifications. In section B, the above changes are reflected and a reindexing of the Segregated Pack sequence. In section C, the three erroneous items are removed and only eight (8) bags are required.
7. All other terms and conditions of this order remain the same.

*** END OF NARRATIVE A 002 ***